

# Inspection Report


This report is created by

**LAUNCH**

## Vehicle Information

VIN: WBAKV220400  
Vehicle manufacturer/model: BMW/X6 xDrive30d  
Year of manufacture: 2015.05  
Odometer: 60367  
Vehicle Software Version: V51.00

## Inspection Organization

Name: BPC Auto Inspect  
Address:  
Contact Number:  
SN: 979390  
Time and date of inspection: 02/17/2023 10:46:32  
Inspection Location: 

## Inspection Result

There are 1 issues for Safety and Security system:

1.EPS Voltage Supply: Undervoltage Control Unit, Reduction Of Steering Assistance

Inspections are normal for Power system

- GWS (Gear Selector Switch)
- TCM (Transmission Control Module - EGS)
- LMV/VTG (Transfer Case)

Inspections are normal for Safety and Security system

- ABS (Anti-Lock Braking System - DSC)
- SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)

## Professional Report

GWS (Gear Selector Switch)	Normal ^
----------------------------	----------

**DTC Qty (0)**

TCM (Transmission Control Module - EGS)	Normal ^
-----------------------------------------	----------

**DTC Qty (0)**

---

**ABS (Anti-Lock Braking System - DSC)**

Normal ^

---

**DTC Qty (0)**

---

**SRS (Supplemental Inflatable Restraint System - AIRBAG/SGM-SIM)**

Normal ^

---

**DTC Qty (0)**

---

**LMV/VTG (Transfer Case)**

Normal ^

---

**DTC Qty (0)**

---

**EPS (Electronic Power Steering)**

Abnormal 1 ^

---

**DTC Qty (1)**

4823FC

EPS Voltage Supply: Undervoltage Control Unit, Reduction Of Steering Assistance

Intermittent

---

**Disclaimer**

---

This inspection report is for reference only. All data provided in this report is based on static data, detailed dynamic and/or live diagnostic data should be generated by a professional maintenance tool. Launch is not liable for any fault or accident caused thereby.